




Residential Solar Panel Inspection

07/07/2025 11:34 AM



Conditions

Conditions:

Date: 25/07/07

TOD: 11:30AM to 11:45AM PST

Temp: 82.2F

Wind: 1.1mph


Irradiance: >870 w/m2

Notes:

Spot 1, is likely a connection location and stands out as hotter than average.

Spot 4, is a soil spot but does not appear to be affecting the panel significantly.

07/07/2025 11:34 AM



Measurements

Sp1	160.5 °F
Sp2	130.2 °F
Sp3	121.8 °F
Sp4	129.8 °F
Sp5	137.9 °F

Note: Temperatures listed are relative to this image

